
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection Bay Area Branch 690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-017445 Address: 333 Burma Road **Date Inspected:** 28-Sep-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Contractor: **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Mr.Xu Le Fung. **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** Tower and Orthotropic Box Girder (OBG)

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

BAY 10

This QA Inspector performed randomly Visual Inspection and Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6027 (UT) report for this date. The member is identified as OBG Bike path plate. The weld designations reviewed are as follows.

BK004A1-033-009

NDT Notification No-06787

BAY 11

This QA Inspector performed randomly Visual Inspection and Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL- 6028 (MT) report for this date. The member is identified as OBG Bike path plate. The weld designations reviewed are as follows.

10A-BK004A6-022-084, 085, BK004A4-022-001, BK004A7-022-090, 027, 028, 034, 088, 094

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

9A - BK004A6-022-112, 113, NDT Notification No-06789

BK004A4-022-069,

BK004A7-022-054, 060, 051, 112, 200

This QA Inspector observed the following work in progress:

BAY 11

This QA Inspector observed ZPMC qualified welding personnel identified as 054460, 044541, Perform Shielded Metal Arc Welding (SMAW) on Lift 5 bracket stiffener. Joint identified as ND1-BRSA5-2-11A, 7A. ZPMC CWI Identified as Yu Dong Ping. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3213-Tc-U4b.

SMAW Process Repair welding:

This QA Inspector observed ZPMC qualified welding personnel identified as 066326 Perform Shielded Metal Arc Welding (SMAW) on West Tower lift 5 Grillage plate. Joint identified as WSD1-TL5-4E/F-1A/B. ZPMC QC Identified as Zhao Mao Mao with Temporary welding repair report WRR-T-WR3653. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-485-SMAW-3G (3F) Repair. For more information see below attached picture number 1.

SMAW Process Repair welding:

This QA Inspector observed ZPMC qualified welding personnel identified as 046769 Perform Shielded Metal Arc Welding (SMAW) on East Tower lift 5 Grillage plate. Joint identified as ESD1-TL5-2E/F-20A/B. ZPMC QC Identified as Zhao Mao Mao with Temporary welding repair report WRR-T-WR3663. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-485-SMAW-3G (3F) Repair.

OBG Bike path stringer plate SMAW process:

This QA Inspector observed ZPMC qualified welding personnel identified as 040655, Perform Shielded Metal Arc Welding (SMAW) on OBG bike path stringer plate. Joint identified as BK004A8-018-106, 107. ZPMC QC Identified as Shao Hai Long. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2113.

BAY 10

SMAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 056200, 056364 Perform Shielded Metal Arc Welding (SMAW) on Façade connection plate. Joint identified as ND1-SFSA4-328A/B-1, 2, 3, 5, 6, 7, 8, 9, 10, 11, 12. ZPMC QC Identified as Yin Chun Fang. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2114.


OBG Bike path stringer plate FCAW process:

This QA Inspector observed ZPMC qualified welding personnel identified as 053869, Perform Flux Core Arc Welding (FCAW) on OBG bike path stringer plate. Joint identified as BK004-028-214, 215, 129, 144. ZPMC QC Identified as Lijun. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2131 and WPS-B-T-2133.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng Phone: 15921845703, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Shailesh	Quality Assurance Inspector
Reviewed By:	Clifford, William	QA Reviewer